

**Flood Control Project Maintenance
Levee Inspections****2009 Channel Summary Report****Overall Unit and Item Ratings****Fairfield Suisun Sewer District**

Laurel Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

Ledgewood Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

McCoy Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

Union Avenue Diversion

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2009 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Laurel Creek

Channel Rating	A
Date of Inspection	7/7/2009
DWR Inspector	John Williamson
Accompanied By	

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Cement Hill Rd	Up	Vegetation & Obstructions		A		38.279793 ° -122.018267 °	Y	1
2		Up	Shoaling / Sedimentation		A		38.279793 ° -122.018267 °		2
3		Up	Erosion / Bank Caving		A		38.279793 ° -122.018267 °		3
4		Up	Revetments		A		38.279793 ° -122.018267 °		4
5		Up	Encroachments		A		38.279793 ° -122.018267 °		5
6		Down	Vegetation & Obstructions		A		38.279793 ° -122.018267 °	Y	6
7		Down	Shoaling / Sedimentation		A		38.279793 ° -122.018267 °		7
8		Down	Erosion / Bank Caving		A		38.279793 ° -122.018267 °		8
9		Down	Revetments		A		38.279793 ° -122.018267 °		9
10		Down	Encroachments		A		38.279793 ° -122.018267 °		10
11	Air Base Parkway	Up	Vegetation & Obstructions		M	Inspector Comments: cattails	38.272625 ° -122.015993 °	Y	11
12		Up	Shoaling / Sedimentation		A		38.272625 ° -122.015993 °		12
13		Up	Erosion / Bank Caving		A		38.272625 ° -122.015993 °		13
14		Up	Revetments		A		38.272625 ° -122.015993 °		14
15		Up	Encroachments		A		38.272625 ° -122.015993 °		15
16		Down	Vegetation & Obstructions		A		38.272625 ° -122.015993 °	Y	16
17		Down	Shoaling / Sedimentation		A		38.272625 ° -122.015993 °		17

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
18		Down	Erosion / Bank Caving		A		38.272625 ° -122.015993 °		18
19		Down	Revetments		A		38.272625 ° -122.015993 °		19
20		Down	Encroachments		A		38.272625 ° -122.015993 °		20
21	Meadowlark Dr	Up	Vegetation & Obstructions		A		38.268240 ° -122.017115 °	Y	21
22		Up	Shoaling / Sedimentation		A		38.268240 ° -122.017115 °		22
23		Up	Erosion / Bank Caving		A		38.268240 ° -122.017115 °		23
24		Up	Revetments		A		38.268240 ° -122.017115 °		24
25		Up	Encroachments		A		38.268240 ° -122.017115 °		25
26		Down	Vegetation & Obstructions		A		38.268240 ° -122.017115 °	Y	26
27		Down	Shoaling / Sedimentation		A		38.268240 ° -122.017115 °		27
28		Down	Erosion / Bank Caving		A		38.268240 ° -122.017115 °		28
29		Down	Revetments		A		38.268240 ° -122.017115 °		29
30		Down	Encroachments		A		38.268240 ° -122.017115 °		30
31	East Tabor Ave	Up	Vegetation & Obstructions		A		38.265262 ° -122.018443 °	Y	31
32		Up	Shoaling / Sedimentation		A		38.265262 ° -122.018443 °		32
33		Up	Erosion / Bank Caving		A		38.265262 ° -122.018443 °		33
34		Up	Revetments		A		38.265262 ° -122.018443 °		34
35		Up	Encroachments		A		38.265262 ° -122.018443 °		35

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
36		Down	Vegetation & Obstructions		A		38.265262 ° -122.018443 °	Y	36
37		Down	Shoaling / Sedimentation		A		38.265262 ° -122.018443 °		37
38		Down	Erosion / Bank Caving		A		38.265262 ° -122.018443 °		38
39		Down	Revetments		A		38.265262 ° -122.018443 °		39
40		Down	Encroachments		A		38.265262 ° -122.018443 °		40
41	Matthew Rd	Up	Vegetation & Obstructions		A		38.259272 ° -122.017533 °	Y	41
42		Up	Shoaling / Sedimentation		A		38.259272 ° -122.017533 °		42
43		Up	Erosion / Bank Caving		A		38.259272 ° -122.017533 °		43
44		Up	Revetments		A		38.259272 ° -122.017533 °		44
45		Up	Encroachments		A		38.259272 ° -122.017533 °		45
46		Down	Vegetation & Obstructions		A	Inspector Comments: cattails	38.259272 ° -122.017533 °	Y	46
47		Down	Shoaling / Sedimentation		A		38.259272 ° -122.017533 °		47
48		Down	Erosion / Bank Caving		A		38.259272 ° -122.017533 °		48
49		Down	Revetments		A		38.259272 ° -122.017533 °		49
50		Down	Encroachments		A		38.259272 ° -122.017533 °		50
51	Blossom Rd	Up	Vegetation & Obstructions		A	Inspector Comments: bridge is clear of trees need to cut and spray small trees	38.253382 ° -122.014862 °	Y	51
52		Up	Shoaling / Sedimentation		A		38.253382 ° -122.014862 °		52

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
53		Up	Erosion / Bank Caving		A		38.253382 ° -122.014862 °		53
54		Up	Revetments		A		38.253382 ° -122.014862 °		54
55		Up	Encroachments		A		38.253382 ° -122.014862 °		55
56		Down	Vegetation & Obstructions		A	Inspector Comments: small trees need to be cut and sprayed	38.253382 ° -122.014862 °	Y	56
57		Down	Shoaling / Sedimentation		A		38.253382 ° -122.014862 °		57
58		Down	Erosion / Bank Caving		A		38.253382 ° -122.014862 °		58
59		Down	Revetments		A		38.253382 ° -122.014862 °		59
60		Down	Encroachments		A		38.253382 ° -122.014862 °		60
61	Worley Rd	Up	Vegetation & Obstructions		A	Inspector Comments: cut and spray small trees	38.253248 ° -122.009732 °	Y	61
62		Up	Shoaling / Sedimentation		A		38.253248 ° -122.009732 °		62
63		Up	Erosion / Bank Caving		A		38.253248 ° -122.009732 °		63
64		Up	Revetments		A		38.253248 ° -122.009732 °		64
65		Up	Encroachments		A		38.253248 ° -122.009732 °		65
66		Down	Vegetation & Obstructions		A	Inspector Comments: cut and spray small trees	38.253248 ° -122.009732 °	Y	66
67		Down	Shoaling / Sedimentation		A		38.253248 ° -122.009732 °		67
68		Down	Erosion / Bank Caving		A		38.253248 ° -122.009732 °		68
69		Down	Revetments		A		38.253248 ° -122.009732 °		69

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

LMR No.	Check Point	View	Item	* Location	** Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
70		Down	Encroachments		A		38.253248 ° -122.009732 °		70

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Gulf Dr. 38.28201 - 122.01947	
johngw_20090723_8.jpg	



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Cement Hill Rd. 38.27979 - 122.01826	
johngw_20090723_9.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Gulf Dr. 38.28201 - 122.01947	
johngw_20090723_10.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Cement Hill Rd. 38.27979 -122.01826	
johngw_20090723_11.jpg	



Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Air Base Parkway 38.27262 -122.-1599	
johngw_20090723_12.jpg	



Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view looking towards Nightingale Dr. 38.27262 -122.01599	
johngw_20090723_13.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Meadowlark Dr. 38.26824 - 122.01711	
johngw_20090723_14.jpg	



Levee Mile Report Line	26
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Meadowlark Dr. 38.26824 - 122.01711	
johngw_20090723_15.jpg	



Levee Mile Report Line	31
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from E. Tabor Ave. 38.26526 - 122.01844	
johngw_20090723_16.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from E. Tabor Ave. 38.26526 - 122.01844	
johngw_20090723_17.jpg	



Levee Mile Report Line	41
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Matthew Rd. 38.25027 - 12.01753	
johngw_20090723_18.jpg	



Levee Mile Report Line	41
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Sunset Ave a spur channel which drains into Laurel Creek 38.25338 - 122.02007	
johngw_20090723_19.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	46
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Matthew Rd. looking towards railroad tracks 38.25928 -122.01752 this is the end of the City of Fairfield's maintenance of the channel. The City of Suisun takes over for the remainder.	
john_gw_20090723_20.jpg	



Levee Mile Report Line	46
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Down stream view from Railroad Ave. 38.25775 - 122.01781	
john_gw_20090723_21.jpg	



Levee Mile Report Line	46
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Sunset Ave a spur draining into Laurel Creek 38.25338 -122.02007	
john_gw_20090723_22.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	51
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Blossom Rd. 38.25338 - 122.01486	
johngw_20090723_23.jpg	



Levee Mile Report Line	56
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Blossom Rd. 38.25338 - 122.01486	
johngw_20090723_24.jpg	



Levee Mile Report Line	61
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Worley Rd. 38.25324 - 122.00973	
johngw_20090723_25.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	66
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Worley Rd. 38.25324 - 122.00973	
johngw_20090723_26.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

Flood Control Project Maintenance**Unit Cover Sheet****2009 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Ledgewood Creek

Channel Rating	A
Date of Inspection	7/7/2009
DWR Inspector	John Williamson
Accompanied By	Bill Carriere

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Astoria Drive	Up	Vegetation & Obstructions		A		38.256147 ° -122.073892 °	Y	1
2		Up	Shoaling / Sedimentation		A		38.256147 ° -122.073892 °		2
3		Up	Erosion / Bank Caving		A		38.256147 ° -122.073892 °		3
4		Up	Revetments		A		38.256147 ° -122.073892 °		4
5		Up	Encroachments		A		38.256147 ° -122.073892 °		5
6		Down	Vegetation & Obstructions		A	Inspector Comments: blackberries need to be mowed and sprayed	38.256147 ° -122.073892 °	Y	6
7		Down	Shoaling / Sedimentation		A		38.256147 ° -122.073892 °		7
8		Down	Erosion / Bank Caving		A		38.256147 ° -122.073892 °		8
9		Down	Revetments		A		38.256147 ° -122.073892 °		9
10		Down	Encroachments		A		38.256147 ° -122.073892 °		10
11	Rockville Road	Up	Vegetation & Obstructions		A	Inspector Comments: need to cut and remove willows and blackberries spray after cutting	38.249960 ° -122.072670 °	Y	11
12		Up	Shoaling / Sedimentation		A		38.249960 ° -122.072670 °		12
13		Up	Erosion / Bank Caving		A		38.249960 ° -122.072670 °		13
14		Up	Revetments		A		38.249960 ° -122.072670 °		14
15		Up	Encroachments		A		38.249960 ° -122.072670 °		15
16		Down	Vegetation & Obstructions		A		38.249960 ° -122.072670 °	Y	16
17		Down	Shoaling / Sedimentation		A		38.249960 ° -122.072670 °		17

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
18		Down	Erosion / Bank Caving		A		38.249960 ° -122.072670 °		18
19		Down	Revetments		A		38.249960 ° -122.072670 °		19
20		Down	Encroachments		A		38.249960 ° -122.072670 °		20
21	Auto Mall Parkway	Up	Vegetation & Obstructions		A		38.247722 ° -122.072105 °	Y	21
22		Up	Shoaling / Sedimentation		A		38.247722 ° -122.072105 °		22
23		Up	Erosion / Bank Caving		A		38.247722 ° -122.072105 °		23
24		Up	Revetments		A		38.247722 ° -122.072105 °		24
25		Up	Encroachments		A		38.247722 ° -122.072105 °		25
26		Down	Vegetation & Obstructions		A		38.247722 ° -122.072105 °	Y	26
27		Down	Shoaling / Sedimentation		A		38.247722 ° -122.072105 °		27
28		Down	Erosion / Bank Caving		A		38.247722 ° -122.072105 °		28
29		Down	Revetments		A		38.247722 ° -122.072105 °		29
30		Down	Encroachments		A		38.247722 ° -122.072105 °		30
31	Woolner Avenue	Up	Vegetation & Obstructions		A		38.242275 ° -122.070478 °	Y	31
32		Up	Shoaling / Sedimentation		A		38.242275 ° -122.070478 °		32
33		Up	Erosion / Bank Caving		A		38.242275 ° -122.070478 °		33
34		Up	Revetments		A		38.242275 ° -122.070478 °		34
35		Up	Encroachments		A		38.242275 ° -122.070478 °		35

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
36		Down	Vegetation & Obstructions		A		38.242275 ° -122.070478 °	Y	36
37		Down	Shoaling / Sedimentation		A		38.242275 ° -122.070478 °		37
38		Down	Erosion / Bank Caving		A		38.242275 ° -122.070478 °		38
39		Down	Revetments		A		38.242275 ° -122.070478 °		39
40		Down	Encroachments		A		38.242275 ° -122.070478 °		40
41	Beck Avenue	Up	Vegetation & Obstructions		A		38.243702 ° -122.066538 °	Y	41
42		Up	Shoaling / Sedimentation		A		38.243702 ° -122.066538 °		42
43		Up	Erosion / Bank Caving		A		38.243702 ° -122.066538 °		43
44		Up	Revetments		A		38.243702 ° -122.066538 °		44
45		Up	Encroachments		A		38.243702 ° -122.066538 °		45
46		Down	Vegetation & Obstructions		A		38.243702 ° -122.066538 °	Y	46
47		Down	Shoaling / Sedimentation		A		38.243702 ° -122.066538 °		47
48		Down	Erosion / Bank Caving		A		38.243702 ° -122.066538 °		48
49		Down	Revetments		A		38.243702 ° -122.066538 °		49
50		Down	Encroachments		A		38.243702 ° -122.066538 °		50
51	Highway 12	Up	Vegetation & Obstructions		A		38.240590 ° -122.062413 °	Y	51
52		Up	Shoaling / Sedimentation		A		38.240590 ° -122.062413 °		52

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
53		Up	Erosion / Bank Caving		A		38.240590 ° -122.062413 °		53
54		Up	Revetments		A		38.240590 ° -122.062413 °		54
55		Up	Encroachments		A		38.240590 ° -122.062413 °		55
56		Down	Vegetation & Obstructions		A		38.240590 ° -122.062413 °	Y	56
57		Down	Shoaling / Sedimentation		A		38.240590 ° -122.062413 °		57
58		Down	Erosion / Bank Caving		A		38.240590 ° -122.062413 °		58
59		Down	Revetments		A		38.240590 ° -122.062413 °		59
60		Down	Encroachments		A		38.240590 ° -122.062413 °		60
61	Cordelia Road	Up	Vegetation & Obstructions			Inspector Comments: NO photo or inspection, road was closed due to construction GPS was taken from Goggle Earth	38.233310 ° -122.058590 °		61
62		Up	Shoaling / Sedimentation				38.233310 ° -122.058590 °		62
63		Up	Erosion / Bank Caving				38.233310 ° -122.058590 °		63
64		Up	Revetments				38.233310 ° -122.058590 °		64
65		Up	Encroachments				38.233310 ° -122.058590 °		65
66		Down	Vegetation & Obstructions				38.233310 ° -122.058590 °		66
67		Down	Shoaling / Sedimentation				38.233310 ° -122.058590 °		67
68		Down	Erosion / Bank Caving				38.233310 ° -122.058590 °		68
69		Down	Revetments				38.233310 ° -122.058590 °		69

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

LMR No.	Check Point	View	Item	* Location	** Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
70			Down Encroachments				38.233310 ° -122.058590 °		70

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Astoria Dr. 38.25614 - 122.07389	
johngw_20090723_39.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Astoria Dr. 38.25614 - 122.07389	
johngw_20090723_40.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from parking lot off Oliver Rd. start of channel. Pipe surfaces from Pennsylvania Ave. Creek detention basin 38.25782 -122.06970	
johngw_20090723_41.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Maintenance has been done at Astoria Dr. 8-18-09	
johngw_20090819_62.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
maintenance has been done at the start of channel off Oliver Rd. 8-18-09	
johngw_20090819_63.jpg	



Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Rockville Rd. 38.24996 - 122.07267	
johngw_20090723_42.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Springfiel Dr. between Astoria and Rockville 38.25473 -122.07369	
johngw_20090723_43.jpg	



Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Rockville Rd. 38.24996 - 122.07267	
johngw_20090723_44.jpg	



Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Springfield Dr. between Astoria and Rockville Rd. 38.25473 -122.07369	
johngw_20090723_45.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Maintenance has been done on Springview Dr. crossing 8-18-09	
johngw_20090819_61.jpg	



Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Auto mall Parkway 38.24772 -122.07210	
johngw_20090723_46.jpg	



Levee Mile Report Line	26
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Auto Mall Parkway 38.24772 -122.07210	
johngw_20090723_47.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	31
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Woolner Ave, 38.24223 - 122.07050	
johngw_20090723_48.jpg	



Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Woolner Ave. 38.24223 - 122.07050	
johngw_20090723_49.jpg	



Levee Mile Report Line	41
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Beck Ave. 38.24369 - 122.06653	
johngw_20090723_50.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek		07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	46
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Beck Ave. 38.24369 - 122.06653	
johngw_20090723_51.jpg	



Levee Mile Report Line	51
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Hwy. 12 38.24059 - 122.06241	
johngw_20090723_52.jpg	



Levee Mile Report Line	56
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Hwy. 12 38.24032 - 122.06258	
johngw_20090723_53.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

Flood Control Project Maintenance**Unit Cover Sheet****2009 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
McCoy Creek

Channel Rating	A
Date of Inspection	7/7/2009
DWR Inspector	John Williamson
Accompanied By	

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	07/22/2009 07/22/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Bella Vista Dr	Up	Vegetation & Obstructions		M	Inspector Comments: cattails	38.253280 ° -122.000670 °	Y	1
2		Up	Shoaling / Sedimentation		A		38.253280 ° -122.000670 °		2
3		Up	Erosion / Bank Caving		A		38.253280 ° -122.000670 °		3
4		Up	Revetments		M		38.253280 ° -122.000670 °		4
5		Up	Encroachments		A		38.253280 ° -122.000670 °		5
6		Down	Vegetation & Obstructions		M	Inspector Comments: cattails	38.253280 ° -122.000670 °	Y	6
7		Down	Shoaling / Sedimentation		A		38.253280 ° -122.000670 °		7
8		Down	Erosion / Bank Caving		A		38.253280 ° -122.000670 °		8
9		Down	Revetments		M		38.253280 ° -122.000670 °		9
10		Down	Encroachments		A		38.253280 ° -122.000670 °		10
11	Emporer Dr	Up	Vegetation & Obstructions		A		38.250738 ° -122.004355 °	Y	11
12		Up	Shoaling / Sedimentation		A		38.250738 ° -122.004355 °		12
13		Up	Erosion / Bank Caving		A		38.250738 ° -122.004355 °		13
14		Up	Revetments		A		38.250738 ° -122.004355 °		14
15		Up	Encroachments		A		38.250738 ° -122.004355 °		15
16		Down	Vegetation & Obstructions		A		38.250738 ° -122.004355 °	Y	16
17		Down	Shoaling / Sedimentation		A		38.250738 ° -122.004355 °		17

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	07/22/2009 07/22/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
18		Down	Erosion / Bank Caving		A		38.250738 ° -122.004355 °		18
19		Down	Revetments		A		38.250738 ° -122.004355 °		19
20		Down	Encroachments		A		38.250738 ° -122.004355 °		20
21	Pintail Ave	Up	Vegetation & Obstructions		A		38.248542 ° -122.006378 °	Y	21
22		Up	Shoaling / Sedimentation		A		38.248542 ° -122.006378 °		22
23		Up	Erosion / Bank Caving		A		38.248542 ° -122.006378 °		23
24		Up	Revetments		A		38.248542 ° -122.006378 °		24
25		Up	Encroachments		A		38.248542 ° -122.006378 °		25
26		Down	Vegetation & Obstructions		A		38.248542 ° -122.006378 °	Y	26
27		Down	Shoaling / Sedimentation		A		38.248542 ° -122.006378 °		27
28		Down	Erosion / Bank Caving		A		38.248542 ° -122.006378 °		28
29		Down	Revetments		A		38.248542 ° -122.006378 °		29
30		Down	Encroachments		A		38.248542 ° -122.006378 °		30
31	Anderson Dr	Up	Vegetation & Obstructions		A	Inspector Comments: cattails	38.241288 ° -122.012057 °	Y	31
32		Up	Shoaling / Sedimentation		A		38.241288 ° -122.012057 °		32
33		Up	Erosion / Bank Caving		A		38.241288 ° -122.012057 °		33
34		Up	Revetments		A		38.241288 ° -122.012057 °		34
35		Up	Encroachments		A		38.241288 ° -122.012057 °		35

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	07/22/2009 07/22/2009	John Williamson

LMR No.	Check Point	View	Item	* Location	** Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
36		Down	Vegetation & Obstructions		A	Inspector Comments: cattails	38.241288 ° -122.012057 °	Y	36
37		Down	Shoaling / Sedimentation		A		38.241288 ° -122.012057 °		37
38		Down	Erosion / Bank Caving		A		38.241288 ° -122.012057 °		38
39		Down	Revetments		A		38.241288 ° -122.012057 °		39
40		Down	Encroachments		A		38.241288 ° -122.012057 °		40

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view at Bella Vista Dr. 38.25329 - 122.00068	
johngw_20090723_27.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view at Bella Vista Dr. 38.25329 - 122.00068	
johngw_20090723_28.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view at Bella Vista Dr. 38.25329 - 122.00068	
johngw_20090723_29.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Emporer Dr. 38.25073 - 122.00435	
johnngw_20090723_30.jpg	



Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Emporer Dr. 38.25073 - 122.00435	
johnngw_20090723_31.jpg	



Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Pintail Ave. 38.24854 - 122.00637	
johnngw_20090723_32.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	26
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Pintail Ave. 38.24854 - 122.00637	
john_gw_20090723_33.jpg	



Levee Mile Report Line	31
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Anderson Dr. looking towards Hwy. 12 38.24129 -122.01205	
john_gw_20090723_34.jpg	



Levee Mile Report Line	31
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Hwy. 12 no access on downstream side 38.24361 -122.01057	
john_gw_20090723_35.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	07/22/2009 07/22/2009	John Williamson

Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Anderson Dr. looking to Suisun Bay 38.24129 -122.01205	
john_gw_20090723_36.jpg	



Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view picture from upstream side of Hwy. 12 between bike path and Hwy. 38.24361 - 122.01057	
john_gw_20090723_37.jpg	



Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Looking downstream towards Anderson Dr. no access on downstream side 38.24361 -121.01057	
john_gw_20090723_38.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

Flood Control Project Maintenance**Unit Cover Sheet****2009 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Union Avenue Diversion

Channel Rating	A
Date of Inspection	7/7/2009
DWR Inspector	John Williamson
Accompanied By	

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.00	07/21/2009 07/21/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	N. Texas St	Up	Vegetation & Obstructions		C	Inspector Comments: There is no upstream, creek is underground, surfaces downstream side of N. Texas St.	38.280582 ° -122.033912 °		1
2		Up	Shoaling / Sedimentation				38.280582 ° -122.033912 °		2
3		Up	Erosion / Bank Caving				38.280582 ° -122.033912 °		3
4		Up	Revetments				38.280582 ° -122.033912 °		4
5		Up	Encroachments				38.280582 ° -122.033912 °		5
6		Down	Vegetation & Obstructions		A	Inspector Comments: There is no upstream to view because channel is underground and surfaces at N. Texas st.	38.280582 ° -122.033912 °	Y	6
7		Down	Shoaling / Sedimentation		A		38.280582 ° -122.033912 °		7
8		Down	Erosion / Bank Caving		A		38.280582 ° -122.033912 °		8
9		Down	Revetments		A		38.280582 ° -122.033912 °		9
10		Down	Encroachments		A		38.280582 ° -122.033912 °		10
11	Camrose Ave	Up	Vegetation & Obstructions		A		38.281668 ° -122.030495 °	Y	11
12		Up	Shoaling / Sedimentation		A		38.281668 ° -122.030495 °		12
13		Up	Erosion / Bank Caving		A		38.281668 ° -122.030495 °		13
14		Up	Revetments		A		38.281668 ° -122.030495 °		14
15		Up	Encroachments		A		38.281668 ° -122.030495 °		15
16		Down	Vegetation & Obstructions		A		38.281668 ° -122.030495 °	Y	16

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.00	07/21/2009 07/21/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
17		Down	Shoaling / Sedimentation		A		38.281668 ° -122.030495 °		17
18		Down	Erosion / Bank Caving		A		38.281668 ° -122.030495 °		18
19		Down	Revetments		A		38.281668 ° -122.030495 °		19
20		Down	Encroachments		A		38.281668 ° -122.030495 °		20
21	Dover Ave	Up	Vegetation & Obstructions		A		38.280990 ° -122.024750 °	Y	21
22		Up	Shoaling / Sedimentation		A		38.280990 ° -122.024750 °		22
23		Up	Erosion / Bank Caving		A		38.280990 ° -122.024750 °		23
24		Up	Revetments		A		38.280990 ° -122.024750 °		24
25		Up	Encroachments		A		38.280990 ° -122.024750 °		25
26		Down	Vegetation & Obstructions		A		38.280990 ° -122.024750 °	Y	26
27		Down	Shoaling / Sedimentation		A		38.280990 ° -122.024750 °		27
28		Down	Erosion / Bank Caving		A		38.280990 ° -122.024750 °		28
29		Down	Revetments		A		38.280990 ° -122.024750 °		29
30		Down	Encroachments		A		38.280990 ° -122.024750 °		30
31	Gulf Dr	Up	Vegetation & Obstructions		A		38.281002 ° -122.020570 °	Y	31
32		Up	Shoaling / Sedimentation		A		38.281002 ° -122.020570 °		32
33		Up	Erosion / Bank Caving		A		38.281002 ° -122.020570 °		33
34		Up	Revetments		A		38.281002 ° -122.020570 °		34

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.00	07/21/2009 07/21/2009	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
35		Up	Encroachments		A		38.281002 ° -122.020570 °		35
36		Down	Vegetation & Obstructions		A		38.281002 ° -122.020570 °	Y	36
37		Down	Shoaling / Sedimentation		A		38.281002 ° -122.020570 °		37
38		Down	Erosion / Bank Caving		A		38.281002 ° -122.020570 °		38
39		Down	Revetments		A		38.281002 ° -122.020570 °		39
40		Down	Encroachments		A		38.281002 ° -122.020570 °		40

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from N. Texas Street, 38.28058 -122.03391	
johngw_20090723_1.jpg	



Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
upstream view from Camrose Ave.38.28166 - 122.03049	
johngw_20090723_2.jpg	



Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Camrose Ave. 38.28166 - 122.03049	
johngw_20090723_3.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Dover Ave. 38.28099 - 122.02475	
johngw_20090723_4.jpg	



Levee Mile Report Line	26
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Dover Ave. 38.28099 - 122.02475	
johngw_20090723_5.jpg	



Levee Mile Report Line	31
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Upstream view from Gulf Dr. 38.28100 - 122.02057	
johngw_20090723_6.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2009

Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.00	07/21/2009 07/21/2009	John Williamson

Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
Downstream view from Gulf Dr. 38.28100 - 122.02057	
johngw_20090723_7.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected